

LA-UR-21-20833

Approved for public release; distribution is unlimited.

Title: GRING18 Corrosion Characterization

Author(s): Duque, Juan G.
Narlesky, Joshua Edward

Intended for: Report

Issued: 2021-02-01

Disclaimer:

Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by Triad National Security, LLC for the National Nuclear Security Administration of U.S. Department of Energy under contract 89233218CNA000001. By approving this article, the publisher recognizes that the U.S. Government retains nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes. Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Department of Energy. Los Alamos National Laboratory strongly supports academic freedom and a researcher's right to publish; as an institution, however, the Laboratory does not endorse the viewpoint of a publication or guarantee its technical correctness.

GRING18 Corrosion Characterization

Juan G. Duque, Josh Narlesky

Special thanks to Ed Romero for helping with sample transport and Ken Wilson for sectioning the Hagan piece



Managed by Triad National Security, LLC for the U.S. Department of Energy's NNSA

Experimental Objectives

- Image contaminated samples
- Obtain distributions of features on samples

Inside PF4

- Qualitative set of images
- Good for identifying samples with features of interest

LCM images

- Quantitative set of images
- Depth distributions can be obtained



GRING18 Camera Photos



Courtesy TA55 Photo Team

Macro Photos

Glove-box (GB) microscope



Machined area of wall has areas that appear dull due to general corrosion. The general corrosion extends for about 1 cm below the weld.







Microscopic photos were taken above, on, and below the weld to the bottom of the wall piece.

NOTE: All microscopic images that follow are rotated 90 degrees to the right.

Survey of Wall Piece

Glove-box (GB) microscope

(10x
magnification)
Inside glove box
in PF4




Just below the weld, the wall has eroded areas with numerous corrosion pits. Pits ranged in size from 40 up to 100 microns in diameter. The highest concentrations of pits were observed within 1 cm of the weld.

Ratio of depth/diameter is about 2

Survey of Wall Piece

Inside glove box in PF4




Largest pits observed just below weld.


No pits observed on weld.

Very small pits on machined surface above weld.


(20x)



(5x magnification)






(20x)




GRING18 LCM Images

Issues with imaging




Small pits
Light surface corrosion

Corrosion appears to be different at both zones




Larger pits
Lots of surface corrosion
Significant amount of pit agglomerate




Surface Damage



Different surface finish
Appear to have different pit depths and diameters at different zones



Corrosion Characteristics




Area with significant surface damage, ~1600 um from weld, most likely due to heat affected zone, however pit depths are similar to those below that area

For single pits, pit diameters:



- * Zone 1 are from few microns up to 30um
- * Zone 2 are from few microns up to ~85um

Lots of pit agglomerates in zone-2

Pit Depth Statistics




- Bimodal pit distribution
- Indication that surface has a significant effect on corrosion





Corrosion Pits Diameter Vs Depth

TROUGH PITS



SIDEWAY PITS



Two different slopes

Zone 1 pits tend to be deeper than they are wide.

Zone 2 pits are wider than they are deep.

Unable to determine with surface images

Observations

- No cracks observed
- Corrosion above/below weld is different. Likely due to differences in the steel.
 - GB microscope
 - Zone 2 pits ratio were closer to 2.
 - LCM
 - Pits above weld are smaller in diameter and depth
 - Pits below weld are larger in diameter and depth
 - Diameter/depth ratio for pits below weld is >1 .
 - This may be a good thing because in-GB screening measurements would be conservative if we assume 1.

The depths measured with GB-microscope aren't as close to LCM as hoped.

- Need to measure other cans to see if corrosion observations are consistent.
 - Therefore recommend cleaning and imaging 16H1, 18H7, and 19H5. We said we would do this last year. 18H7 and 19H5 show mostly surface erosion, but the LCM is so much better and you probably could get pit distributions. Because those are the worst 3 observed in surveillance, we definitely want to look for cracks.